

# IATSE 8 General Work Rules for Outdoor Venues 2016

- Hard Hats and Safety Boots must be worn at all times. If you do not have a Hard Hat we will provide one. Gloves are also recommended.
- No cell phones or smoking on the site (This includes smoking substitutes).
- No riding Bicycles or Skateboards during work hours.
- No Headphones, earbuds or playing of radios on worksite.
- Drink Water and Gatorade to keep hydrated.
- Use walkways provided by security to avoid moving vehicles.
- Don't walk behind a moving vehicle or forklift. No riding on Forklifts and no walking under the load of a Forklift.
- Be mindful to avoid vehicles while crossing the street. A Safety Shirt or Safety Vest must be worn when working in street.
- Look out for each other, if someone looks dazed or confused tell your Head.
- If you are climbing more than 6 feet you must use a harness. Inspect your Harness Daily.
- Safety off all tools in the air.
- When the Crane is in use keep talking to a minimum, only one person signals the crane at a time. You must be certified to signal the crane.
- You must wear Safety Goggles when using Power Tools or Cutting.
- You must wear a Hi Viz Shirt or Safety Vest when working in the street.
- 2 people pushing all boxes going up or down a ramp, 4 on larger boxes.
- Put your foot up behind you when you stop to avoid having your ankle run over.
- If it rains work at half speed. In the event an evacuation is called go inside the building not in a tent. Rain Jackets and Rain Pants are recommended.

- If you are hurt on the job you must report it immediately to a Head of Department.
- If you are impaired for any reason you will be sent home.